


ENCODER PIN / CABLE CONNECTIONS



PIN	SIGNAL	PEI CABLE
1	0 V	WHITE-1
2	+ V	BLACK-1
3	A +	BLACK-2
4	B +	BLACK-3
5	Not Used	
6	A -	WHITE-2
7	B -	WHITE-3
8	Not Used	
9	Not Used	

IMPORTANT !

Cable shield must be grounded on ONE END ONLY.
Preferably at the motor end.